Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	250102
Date	02 January 2025 (Thursday)
Time	09:30 – 16:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality	
	No environmental deficiency was identified during site inspection.	
	C. Air Quality	
	No environmental deficiency was identified during site inspection.	
	D. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	E. Waste/Chemical Management	
	No environmental deficiency was identified during site inspection.	
	F. Visual and Landscape	
	No environmental deficiency was identified during site inspection.	
	G. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	H. Marine Ecology	
	No environmental deficiency was identified during site inspection.	
	I. Others	
	• Follow up on the previous session (Ref No.:241227), all the items have been rectified.	

	Name	Signature	Date
Recorded by	William Yeung		02 January 2025
Checked by	Karina Chan	Zolle	06 January 2025

Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	250109
Date	09 January 2025 (Thursday)
Time	09:30 – 16:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality No environmental deficiency was identified during site inspection.	
250109-EP458-R1	C. Air Quality Different stacks of cement bags should be covered properly to minimize dust emission.	C20
	 D. Construction Noise Impact No environmental deficiency was identified during site inspection. 	
	 E. Waste/Chemical Management No environmental deficiency was identified during site inspection. 	
	 F. Visual and Landscape No environmental deficiency was identified during site inspection. 	
	 G. Permits/Licences No environmental deficiency was identified during site inspection. 	
	 H. Marine Ecology No environmental deficiency was identified during site inspection. 	
	 I. Others No environmental deficiency was identified in previous session (Ref No.: 250102). 	

	Name	Signature	Date
Recorded by	William Yeung		09 January 2025
Checked by	Karina Chan	Jalle	13 January 2025

Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	250116
Date	16 January 2025 (Thursday)
Time	09:30 – 16:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality	
	No environmental deficiency was identified during site inspection.	
	C. Air Quality	
	No environmental deficiency was identified during site inspection.	
	D. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	E. Waste/Chemical Management	
	No environmental deficiency was identified during site inspection.	
	F. Visual and Landscape	
	No environmental deficiency was identified during site inspection.	
	G. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	H. Marine Ecology	
	No environmental deficiency was identified during site inspection.	
	I. Others	
	• Follow up on the previous session (Ref No.:250109), all the items have been rectified.	

	Name	Signature	Date
Recorded by	William Yeung	B	16 January 2025
Checked by	Karina Chan	Zalle	20 January 2025

Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	250123	
Date	23 January 2025 (Thursday)	
Time	09:30 – 16:30	

Ref. No.	Non-Compliance	
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality	
	No environmental deficiency was identified during site inspection.	
	C. Air Quality	
	No environmental deficiency was identified during site inspection.	
	D. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	E. Waste/Chemical Management	
	No environmental deficiency was identified during site inspection.	
	F. Visual and Landscape	
	• No environmental deficiency was identified during site inspection.	
	G. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	H. Marine Ecology	
	No environmental deficiency was identified during site inspection.	
	I. Others	
	• No environmental deficiency was identified in previous session (Ref No.: 250116).	

	Name	Signature	Date
Recorded by	William Yeung	B	23 January 2025
Checked by	Karina Chan	Zalle	27 January 2025

Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	250128
Date	28 January 2025 (Tuesday)
Time	09:30 – 16:30

Ref. No.	Non-Compliance	
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality No environmental deficiency was identified during site inspection.	
	C. Air QualityNo environmental deficiency was identified during site inspection.	
	 D. Construction Noise Impact No environmental deficiency was identified during site inspection. 	
	 E. Waste/Chemical Management No environmental deficiency was identified during site inspection. 	
	 F. Visual and Landscape No environmental deficiency was identified during site inspection. 	
	 G. Permits/Licences No environmental deficiency was identified during site inspection. 	
	 H. Marine Ecology No environmental deficiency was identified during site inspection. 	
	 I. Others No environmental deficiency was identified in previous session (Ref No.: 250123). 	

	Name	Signature	Date
Recorded by	William Yeung	B	28 January 2025
Checked by	Karina Chan	Zalle	03 February 2025