Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	240704
Date	04 July 2024 (Thursday)
Time	09:30 – 16:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality No environmental deficiency was identified during site inspection.	
	C. Air QualityNo environmental deficiency was identified during site inspection.	
	 D. Construction Noise Impact No environmental deficiency was identified during site inspection. 	
240704-EP458-R1	 E. Waste/Chemical Management Drip tray should be provided for chemical containers to prevent leakage. (East Bound) 	<i>E</i> 9
	 F. Visual and Landscape No environmental deficiency was identified during site inspection. 	
	 G. Permits/Licences No environmental deficiency was identified during site inspection. 	
	 H. Marine Ecology No environmental deficiency was identified during site inspection. 	
	 I. Others No environmental deficiency was identified in previous session (Ref No.: 240627) 	

	Name	Signature	Date
Recorded by	Eric Hung		04 July 2024
Checked by	Karina Chan	Zalle	05 July 2024

Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	240711
Date	11 July 2024 (Thursday)
Time	09:30 – 16:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality	
	No environmental deficiency was identified during site inspection.	
	C. Air Quality	
	No environmental deficiency was identified during site inspection.	
	D. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	E. Waste/Chemical Management	
	No environmental deficiency was identified during site inspection.	
	F. Visual and Landscape	
	No environmental deficiency was identified during site inspection.	
	G. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	H. Marine Ecology	
	No environmental deficiency was identified during site inspection.	
	I. Others	
	• Follow up on the previous session (Ref No.:240704), all the items have been rectified.	

	Name	Signature	Date
Recorded by	Eric Hung		11 July 2024
Checked by	Karina Chan	Zalle	12 July 2024

Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	240718
Date	18 July 2024 (Thursday)
Time	09:30 – 16:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality No environmental deficiency was identified during site inspection.	
	 C. Air Quality No environmental deficiency was identified during site inspection. 	
	 D. Construction Noise Impact No environmental deficiency was identified during site inspection. 	
240718-EP458-R1	 E. Waste/Chemical Management Rubbish bin should be covered to avoid odour and mosquitoes. (EVB Basement) 	Elii
	 F. Visual and Landscape No environmental deficiency was identified during site inspection. 	
	 G. Permits/Licences No environmental deficiency was identified during site inspection. 	
	 H. Marine Ecology No environmental deficiency was identified during site inspection. 	
	 I. Others No environmental deficiency was identified in previous session (Ref No.: 240711) 	

	Name	Signature	Date
Recorded by	Eric Hung		18 July 2024
Checked by	Karina Chan	Zalle	19 July 2024

Environmental Team for Trunk Road T2 and Infrastructure Works at the Former South Apron

Checklist Reference Number	240725
Date	25 July 2024 (Thursday)
Time	09:30 – 16:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	B. Water Quality	
240725-EP458-R1	• Stagnant water should be prevented/removed to avoid mosquitoes at EVB LG-1.	<i>B9</i>
	C. Air Quality	
	No environmental deficiency was identified during site inspection.	
	D. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	E. Waste/Chemical Management	
	No environmental deficiency was identified during site inspection.	
	F. Visual and Landscape	
	No environmental deficiency was identified during site inspection.	
	G. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	3	
	H. Marine Ecology	
	No environmental deficiency was identified during site inspection.	
	I. Others	
	• Follow up on the previous session (Ref No.:240718), all the items have been rectified.	

	Name	Signature	Date
Recorded by	Eric Hung		25 July 2024
Checked by	Karina Chan	Zalle	26 July 2024